



Struck-by Toolbox Talk # 2 Struck-by Incident

Incident: In January 2015, an employee working in a trench was struck-by an excavator bucket, which was removing soil from the excavation, resulting in a broken hip. The employee was severely injured and did not return to work for 30 months.



What could have been done to prevent this incident?

- 1. Before beginning trenching or excavation operations, a job hazard analysis (JHA) should be prepared and reviewed by all involved in the operation.
- 2. Daily huddles should be conducted every day to ensure everyone understands where and how the work is taking place.
- 3. Workers should be trained to stand clear of bucket work, at a distance where the bucket cannot accidently strike the worker.
- 4. Operators should be trained not to move the bucket if a worker is inside the swing radius of the bucket.
- 5. If something changes from the plan, stop work and revise and review the plan with the workers involved.
- 6. Ensure workers working around heavy equipment are wearing high visibility, fluorescent outerwear.
- 7. Workers should stay out of the blind spots of a machine, and in a place where they can easily make eye contact with the operator before entering the bucket swing radius.
- 8. All workers should be trained on working around heavy equipment.
- 9. All workers operating machinery should be trained on the specific machine on which they are working.
- 10. Stay alert when working around heavy equipment!

Discussion: Is heavy equipment being used at this site? Have there been any nearmiss or actual incidents at this site? What are we doing at this site to prevent struckby incidents?



